

**From:**  
**To:** (b)(6)  
**Cc:**  
**Subject:** [Non-DoD Source] Base closure Tuesday norEaster  
**Date:** Monday, March 13, 2017 7:13:36 AM

---

(b)(6) I just received word of base closure tomorrow!  
Please advise of site visit.  
R/s

(b)(6)

Sent from my iPhone

> On Mar 8, 2017, at 8:01 AM, (b)(6) wrote:  
>  
> (b)(6)  
> Can you get me updated punch list info,  
> for all punch lists, of progress made towards completion?  
> CCI - P/L  
> Oak point - P/L  
> NAVFAC - P/L  
> MFR FAC - P/L  
>  
> I would like to have a copy(s),  
> For when I visit the site next week.  
> I'll print them here, if you can just email them to me...  
> R/s,  
> (b)(6)  
>  
>  
>  
> -----Original Message-----  
> From: (b)(6)  
> Sent: Wednesday, March 08, 2017 6:17 AM  
> To: (b)(6)  
> Subject: [Non-DoD Source] RE: Vehicle Maintenance Facility IT hardware  
>  
> Thank you (b)(6) have a great day brother!  
>  
> Best regards,  
> (b)(6)  
> Project Superintendent  
>  
> (b)(6)  
> CCI Solutions LLC  
>  
>> -----Original Message-----  
>> From: (b)(6)  
>> Sent: Wednesday, March 08, 2017 7:09 AM  
>> To:  
>> Cc: (b)(6)  
>>  
>> (b)(6)  
>> Subject: RE: Vehicle Maintenance Facility IT hardware  
>>  
>> (b)(6)

>> Thanks for the update, I wasn't trying to imply that CCI hadn't  
>> complied with contractual issues.  
>> I was able to run down some of this last evening, it appears that this  
>> is being handled by our G-6 folks here at MFR.  
>>  
>> Thanks for your time and attention.....  
>> R/s,  
>> (b)(6)  
>>  
>>  
>>  
>> -----Original Message-----  
>> From: (b)(6)  
>> Sent: Tuesday, March 07, 2017 3:37 PM  
>> To:  
>> Cc:  
>> (b)(6)  
>>  
>>  
>> Subject: [Non-DoD Source] RE: Vehicle Maintenance Facility IT hardware  
>>  
>> (b)(6)  
>>  
>> The base (b)(6) inquired this morning about a network switch.  
>> We walked down the system for functionality and have identified the  
>> telephone lines (NIC) have yet to be identified by the base and  
>> punched down on to the block in the IT rm 218 (usually connected by  
>> Base IT), and the fiber patch jumpers (usually connected by Base IT)  
>> are yet to be completed by the base as contractors are excluded from  
>> these activities for security reasons. The inspector (b)(6) was very thorough.  
>> I have requested in the email to (b)(6) further clarification of  
>> identification of the device parameters and verification. (b)(6)  
>> advised me he was 99.98% sure that the item usually is part of the  
>> base IT dept's final connections that contractors are typically  
>> excluded from performing due to security reasons. I have cc (b)(6) or  
>> further inquiry to (b)(6) as I do not have his email.  
>>  
>> CCI has installed the system as per contract requirements and per the  
>> typical security requirements--we are not allowed to work on the  
>> network at any base I have been assigned final connections at network  
>> side either phone or data. All termination devices per plan are  
>> installed and all fiber and copper lines on the devices are properly terminated.  
>>  
>> So what I know is the outside phone lines are not identified, the  
>> final jumpers from the network to our device in rm 218 comm room of  
>> the Admin bldg. are not connected and the network switch that is  
>> configured specific by the base' it are items to be addressed.  
>>  
>> CCI is happy to support the effort in any way we can.  
>>  
>> Best regards,  
>> (b)(6)  
>> Project Superintendent  
>>  
>> (b)(6)  
>>  
>> CCI Solutions LLC  
>>

>>> -----Original Message-----

>>> From: (b)(6)  
>>> Sent: Tuesday, March 07, 2017 3:34 PM  
>>> To:  
>>> Cc: (b)(6)  
>>> Subject: FW: Vehicle Maintenance Facility IT hardware

>>>  
>>> (b)(6)  
>>> I received this from (b)(6) earlier today, Per our conversation,  
>>> we will not be moving into the new VMF until network services have  
>>> been installed (voice and data).  
>>> I thought I understood that all connections (and testing) in support  
>>> of fiber and telephones had been made between the new VMF and the  
>>> Reserve center.  
>>> Can you elaborate, am I missing something.....

>>>  
>>> R/s,  
>>> (b)(6)

>>>  
>>>  
>>>  
>>>  
>>> -----Original Message-----

>>> From: (b)(6)  
>>> Sent: Tuesday, March 07, 2017 12:44 PM  
>>> To:  
>>> CT  
>>>  
>>>  
>>> (b)(6)  
>>> (b)(6)  
>>>  
>>>  
>>> Subject: Vehicle Maintenance Facility IT hardware

>>>  
>>> Good morning.  
>>>  
>>> 6th Comm Bn has the new Vehicle Maintenance Facility completed.  
>>> Currently  
>>> the building is ready to be occupied with the exception of the IT  
>>> hardware and phone connectivity. Currently the building has wall  
>>> ports connected to a patch panel and a fiber terminator with a  
>>> connection to the comm closet room 218 in the main building.(debark  
>>> point for HTC). Attached please find the email from (b)(6) the  
>>> onsite  
>>> contractor lead for the VMF.  
>>>  
>>> The following RFIs are submitted:  
>>> Who is responsible for procuring the switch in the VMF?  
>>> Who is responsible for configuring the switch in the VMF?  
>>> Who is responsible for connecting the switch to the patch panel?  
>>>  
>>> Who is responsible for the new phone connections in the VMF?  
>>> Who is coordinating with the telco installation for the new phone  
>>> services in the bldg?  
>>> When will lines be added IOT tie in the VMF?  
>>>

>>> Respectfully Submitted,

>>>

>>> (b)(6) USMC

>>> Cyber Network Operations Engineer

>>> Inspector-Instructor Staff

>>> 6th Communication Battalion

>>> Comm (b)(6)

>>

>>

>> \_\_\_\_\_

>>

>> CCI-Alliance Confidentiality notice: This message is intended only for

>> the person to whom addressed in the text above and may contain

>> privileged or confidential information. If you are not that person,

>> any use of this message is prohibited. We request that you notify us

>> by reply to this message, and then delete all copies of this message including any contained in your reply.

>> Thank you.

>>

>> -----

>>

>> This email has been scanned for spam and viruses by Proofpoint Essentials.

>> Visit the following link to report this email as spam:

>> [https://us3.proofpointessentials.com/index01.php?mod\\_id\\_&mod\\_option=](https://us3.proofpointessentials.com/index01.php?mod_id_&mod_option=gitem&mail_id_88974971-887qydMQPqLy&r_address=odges%40cci-alliance.com&report=)

>> gitem&mail\_id\_88974971-887qydMQPqLy&r\_address=odges%40cci-

>> alliance.com&report=

>

> \_\_\_\_\_

>

> CCI-Alliance Confidentiality notice: This message is intended only for the person to whom addressed in the text above and may contain privileged or confidential information. If you are not that person, any use of this message is prohibited. We request that you notify us by reply to this message, and then delete all copies of this message including any contained in your reply. Thank you.

>

> -----

>

> This email has been scanned for spam and viruses by Proofpoint Essentials. Visit the following link to report this email as spam:

> [https://us3.proofpointessentials.com/index01.php?mod\\_id\\_&mod\\_option=gitem&mail\\_id\\_88978091-](https://us3.proofpointessentials.com/index01.php?mod_id_&mod_option=gitem&mail_id_88978091-31fULT%2BHpC9G&r_address=odges%40cci-alliance.com&report=)

> 31fULT%2BHpC9G&r\_address=odges%40cci-alliance.com&report=

\_\_\_\_\_

CCI-Alliance Confidentiality notice: This message is intended only for the person to whom addressed in the text above and may contain privileged or confidential information. If you are not that person, any use of this message is prohibited. We request that you notify us by reply to this message, and then delete all copies of this message including any contained in your reply. Thank you.